


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	6/12/2012	1925		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #3	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	6/12/2012 0700
	Position:	Operations Section Chief	To:	6/12/2012 1925
7. Personnel Roster Assigned				
Name	ICS Position	DUTY CELL		
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Marc Wahrer	SOTF#3			
8. Activity Log				
Activity Area	River Section(s) Assessed –Designated target areas and delineations in the sediment traps 19.25 and 28.25 and a couple of points just upstream of 19.25 area		LAT Various (DD.MMMM)	LAT Various (DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team #3 Activity:</u></p> <p>SOTF-3 Marc Wahrer oversaw work of Enbridge Team C. Team included Colin McGuire (Tetra Tech), Eric Ricci (LBG), and Andrew Castor (MDEQ). Assessed a total of 39 poling and delineation points at sediment traps 19.25 and 28.25 and a few miscellaneous points upstream of 19.25.</p> <p>Sediment trap 19.25 (19.25L1, 19.25S, 19.15S) Assessed 27 poling points (target areas and delineations) in the sediment trap 19.25 area. Poling results included a total of 3 heavy points out of 27, 6 moderate points out of 27, 14 light points out of 27 and 2 none points out of 27 and 2 dry locations. Heavy and moderate areas in the upstream section of 19.25 sediment trap. All the temperatures were above 60 degrees except 5 locations.</p> <p>Upstream of 19.25 points – 19.45N, 19.47T, 19.64T and 20.10S Poling results included a total of 0 heavy points out of 6, 0 moderate points out of 6, 4 light points out of 6 and 2 none points out of 6. All the temperatures were above 60 degrees.</p> <p>Sediment trap 28.25</p>			

	Only got to work this location for about 1.5 hours. Assessed 8 poling points (target areas and delineations) in the sediment trap 28.25 area. Poling results included a total of 3 heavy points out of 8, 1 moderate points out of 8, 2 light points out of 8 and 0 none points out of 8 and 2 dry locations. All the temperatures were above 60 degrees.
Health and Safety Issues	.
Comments	